



Available Position

CNC Lathe Machinist / 2nd Shift

Reports to: Shop Supervisor

Job Responsibilities/Activities:

- Set up Machines as instructed
- Operate Machines as needed
- Responsible for in-process inspection reports
- Responsible for accurate time tracking and piece count

Required Skills, Competencies, Authorities and Training Needs:

- 5 to 10 years relevant Machine shop experience setting up CNC 2 axis lathes
- Experience with multi-axis live tooling Lathes
- Knowledge of SURFCAM CAD/CAM software
- Proficient with common inspection equipment
- Basic computer skills
- Ability to work unsupervised